

UNDER VEHICLE

Pass Att Fail N/A



REAR SHOCKS / REAR SUBFRAME /
SUSPENSION



DRIVE SHAFT / CV AXLES / CV BOOTS
(VISUAL INSPECTION FOR LEAKS)

Pass Att Fail N/A



FRONT SHOCKS / SUSPENSION



DIFFERENTIAL (CHECK CONDITION AND
LEAKS)



MUFFLER / EXHAUST / MOUNTING



FLUID LEAKS (OIL / TRANSMISSION /
COOLANT)

ADDITIONAL COMMENTS

ADDITIONAL SUGGESTED SERVICES

ITEMS REQUIRING IMMEDIATE ATTENTION

BATTERY CAPACITY TEST

FAIL TEST * ~ BATTERY REPLACEMENT

COOLING SYSTEM HOSES

LEAKING * UPPER AND LOWER RADIATOR HOSES THERMOSTAT REPLACE

\$ 671

FLUID LEAKS (OIL / TRANSMISSION / COOLANT)

LEAKING * BOTH VALVE COVER GASKETS REPLACE

\$ 1,133

REAR SHOCKS / REAR SUBFRAME / SUSPENSION

BUSHING LEAKING * REAR SUB FRAME REPLACE

\$ 3,319

ADDITIONAL SERVICE REPAIR

LEAKING * TIMING COVER RESEAL

\$ 2,751

ADDITIONAL SERVICE REPAIR

LEAKING * POWER STEERING RACK REPLACE

\$ 2,732

ADDITIONAL SERVICE REPAIR

ALIGNMENT * ~ ALIGNMENT (4 WHEEL)

\$ 129.99

ITEMS REQUIRING ATTENTION SOON

REAR BRAKES

PADS GET TO LOW * ~ BRAKES OEM REPLACE REAR PADS RESURFACE ROTORS

\$ 319.99